

**Secret**

NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER



25X1

**Imagery analysis report**

# **GALOSH ABM Canister Shelters Under Construction at Moskva ABM Launch Complexes, USSR (S)**

**Secret**

WNINTEL

Z-20098/80  
IAR-0237/80  
SEPTEMBER 1980  
Copy 167

**Page Denied**

SECRET

25X1

## GALOSH ABM CANISTER SHELTERS UNDER CONSTRUCTION AT MOSKVA ABM LAUNCH COMPLEXES, USSR (S)

1. (S/D) A GALOSH ABM canister shelter (Figure 1) was erected at Moskva ABM Launch Complex E05 [ ] in the USSR between [ ] Although no other shelters have been erected, arched roof sections and wall sections for at least one more were at complex E05. Similar sections, enough for two canister shelters, were at each of the three other ABM launch complexes in the Moscow area. 25X1

2. (S/D) At complex E05, four concrete shelter bases were constructed south of the missile handling building. The [ ] shelter was constructed on the base closest to the missile handling building. This prefabricated shelter consists of 12 arched roof sections, 24 wall sections, and two end sections. At least one of the end sections has a plug-type door for environmental control. A steamline connects the shelter and the missile handling building. 25X1

3. (S/D) Components for at least one more shelter were stacked next to the apron of the missile handling building. They were first observed on [ ] and remained there through [ ] 25X1  
[ ] 25X1

4. (S/D) Components for two canister shelters (Figure 2) were brought to Moskva ABM Complex E33 [ ] between [ ] These components were stacked 25X1  
along the tree line west of the missile handling building and have remained unchanged since [ ] 25X1  
[ ] No shelter bases have been constructed at the complex. 25X1

5. (S/D) At Moskva ABM Launch Complex E31 [ ] Figure 3) several components 25X1  
were first seen stored just off the south end of the service road south of the missile handling building in March 1980. Between [ ] additional components were delivered and stored in the 25X1  
same location where they remained through [ ] No shelter bases have been constructed at the 25X1  
complex.

6. (S/D) At Moskva ABM Launch Complex E24 [ ] Figure 4), a few components were 25X1  
near one of the dismantled launcher positions on [ ] Enough components for at least one, and 25X1  
possibly two, shelters had been stored near several of the dismantled launcher positions by [ ] 25X1  
[ ] No shelter bases have been constructed at this complex. 25X1

7. (S/D) On [ ] seven of the arched roof sections were at Moskva ABM Support Facility 25X1  
Borovsk [ ] Figure 5). They were not present on [ ] No wall sections or shelter 25X1  
bases were at this facility.

(S) Comments and queries regarding this report are welcome. They may be directed to [ ] Soviet 25X1  
Strategic Forces Division, Imagery Exploitation Group, NPIC, [ ] 25X1

**Page Denied**

Next 3 Page(s) In Document Denied

**Secret**

**Secret**